

ADVANCED MATERIALS TECHNOLOGIES



Antierosion Coatings

The proposed cover depicts a dolomite sculpture: The left half shows how the passage of time has caused erosion because of Climatic agents (mainly rainfall and temperatures changes). In detail on this side, the stone has deep pores and is cracked. On the right half, the graphene oxide coating protects and preserves the sculpture in its original state. More details can be found in article 2300486 by José M. González-Domínguez, María Fernández-Raga, and co-workers.